

Flowcode

AVR - Verification errors - Flowcode v4 v5

When using Flowcode AVR to program your AVR device you may get a warning after programming stating "verification error" and "content mismatch".

This problem can be solved by checking a number of different causes.

a) If you have a large array of 256 bytes or larger that is initialised to 0, 255 or completely uninitialised then this may cause programming problems. A simple work around is to initialise to a different value or change the size of the array

b) If you are using custom hardware or a 20MHz device then you may be programming the device too slowly via the programming tool. To change the programming rate goto your "Flowcode AVR V4\Tools\MX_bats" folder, right click the avrc.bat file and select edit. Change the lines that start "@SET AVRDUDEcmd" so that there is a "-B 6" before the -c. The 6 is the delay in us between programming bytes. The default setting is defined by your programming tool but is normally around 8us.

You should end up with something like this.

```
@SET AVRDUDEcmd="%~dp0..\AVRDUDEusb\avrdude.exe" -p %2 -P %DUDEPort%  
-B 6 -c %Programmer% -U flash:w:%5
```

```
@SET AVRDUDEcmd="%~dp0..\AVRDUDEusb\avrdude.exe" -p %2 -P %DUDEPort%  
-B 6 -c %Programmer% -u
```

Unique solution ID: #1048

Author: DavidA

Last update: 2015-03-31 16:08