

# Flowcode

## Config 8L error when compiling - Flowcode v5

The problem is caused by 2 different versions of the PPP programming software sharing the same location for their registry data.

There are two workarounds:

- 1) The first is simply to go into the configuration screen in Flowcode V5 and click "OK" (Build...Project Options...Configure Chip...OK) - this will put the missing information into the registry.
- 2) An alternative fix is to change the "config slot" used by Flowcode V5 by editing the Programmer tab of the "Compiler Options" window as shown in this image.

Unique solution ID: #1053

Author: DavidA

Last update: 2015-03-31 17:28