


Every second loop are terrible signals? Why?



I2C in software mode on pins A7/B10 reads in a loop